
OP Emergency Operations Damage Assessment

- Step 1 Determine extent of damage area (QuickCapture)
- Step 2 Create maps and divide damage area into inspection zones
- Step 3 Identify structures and create address list
- Step 4 Create EnerGov request and inspection cases for each building with damage
- Step 5 Inspect damaged structures (iG Enforce)
- Step 6 Create dynamic maps and statistics
- Step 7 Create final reports
 - Individual Structure Report
 - Summary Report

Step 1 - Determine extent of damage area (News Feeds)




Step 1 - Determine extent of damage area (News Feeds)



Step 1 - Determine extent of damage area (QuickCapture)





Step 2 - Create maps and divide damage area into

inspection zones




Step 3 - Identify structures and create address list

TaxPropID	Site Address (SALine1)	Secondary SiteAddress	Own1Name	Own2Name	OALine1	OALine2	ImprValue	Land Use (LBCSFunDsc)	Team Staff
NF251506-1028	19330 HARDY ST		WELLS, LOREE L.	WELLS, MICHAEL W.	19330 HARDY ST	STILWELL, KS 66085	196660	Single family residence	1 Brandon
NF251506-1040	19113 HARDY ST		STAHL, PETER		19113 HARDY ST	STILWELL, KS 66085	258480	Single family residence	1 Brandon
NF251506-1043	19290 HARDY ST		HOLZER, VINCENT		19290 HARDY ST	OVERLAND PARK, KS 66085	185200	Single family residence	1 Brandon
NP73820000 0013	8610 W 193RD TER		MACGEE, BRIAN J	MACGEE, RITA C.	8610 W 193RD TER	STILWELL, KS 66085	186840	Single family residence	1 Kyle
NP73820000 0021	8409 W 193RD TER		THIES, STEPHEN E	THIES, JEANIE E.	8409 W 193RD TER	STILWELL, KS 66085	170900	Single family residence	1 Kyle
NP73820000 0023	19369 HADLEY ST		BOTT, DARRELL D	BOTT, CHRISTINA A.	19369 HADLEY ST	STILWELL, KS 66085	221980	Single family residence	1 Vic
NF251506-1012	19102 HARDY ST		KILCOYNE, JOHN F	Ŧ.	19102 HARDY ST	STILWELL, KS 66085	197030	Single family residence	1 Brandon
NF251506-1018	19321 HARDY ST		RYUN, KENT A.	RYUN, MARILYN F.	19201 HARDY ST	STILWELL, KS 66085	7750	Farming / ranch land (with Ag	g 1 Brandon
NF251506-1033	19174 HARDY ST		HOUSEHOLDER, J	HOUSEHOLDER, JOY	19174 HARDY ST	STILWELL, KS 66085	235260	Single family residence	1 Brandon
NP73820000 0005	19228 HADLEY ST		TOOTLE, GEORGE	R.	19228 HADLEY ST	STILWELL, KS 66085	198160	Single family residence	1 Vic


Step 4 - Create EnerGov request and inspection cases for each building with damage



Step 5 - Inspect damaged structures (iG Enforce)




Step 6 - Create dynamic maps and statistics



Step 7 - Create final reports

Overland Park, K		/16/2021 to 3/17/2021						
CASE NUMBER	1 (1) 1 (1) (1) (1) (1) (1) (1) (1) (1)		DAMAGE ASSESSMENT		DAMA(VALU	70.00	UN	NITS
Other RQDA-000474-2021		Other	Safe			\$0.00		1
SubTo	otal: Other		1 Cases	\$0.00	Total Damages		1 1	Units
Single Family Reside RQDA-000478-2021 RQDA-000473-2021	ence 19335 HARDY ST 19102 HARDY ST	Single Family Residence Single Family Residence	Habitable Safe		\$53,	193.00 \$0.00		1
RQDA-000439-2021 RQDA-000451-2021	8610 W 193RD TER 8652 W 193RD TER	Single Family Residence Single Family Residence	Safe Safe			052.00 850.00		1
SubTotal: Single Family Residence			37 Cases	\$201,112.00	Total Damages	3	7 I	Units
GRAN	ND TOTALS:		38 Cases	\$201,112.00	Total Damages	3	8 T	Units
	Totals By	Safe	37 Cases	\$147,919.00	Total Damages		37	Units
	Damage Assessment	Habitable	1 Cases	\$53,193.00	Total Damages		1	Units
		Limited Entry	0 Cases		Total Damages			Units
		Unsafe	0 Cases		Total Damages			Units



Questions?